

**TEXAS COMMISSION ON JAIL STANDARDS
JAIL INSPECTION REPORT**

Facility Name: Midland County Jail

Date: February 12, 2020

Item	Section	Paragraph	Comments
1	279	.3	<p>Facility Maintenance. Preventive maintenance, to include necessary repairs, shall be conducted to ensure a safe, secure, and sanitary facility.</p> <p>While conducting the walk-through of the facility, the following maintenance issues were identified:</p> <p><u>G</u></p> <p><u>Block</u> - Mop sink clogged and no water available from faucet.</p> <p><u>H Block</u> - 2 toilets clogged, 1 shower clogged, 1 shower constantly running.</p> <p><u>J Block</u> - Sheet rock needs to be replaced on terminal frame, electric covers need to be placed on holes by phone wall, 3 showers down (either clogged or constantly running).</p> <p><u>Tent/Sprung Structure</u> - Hot water does not work on 1 shower, 2 showers do not turn on and they are clogged, mop sink clogged, metal by phones separated from the wall, washer is leaking in laundry room.</p> <p><u>Hallway</u> - Light bulbs need to be replaced between 518-520 doors</p> <p><u>F Block</u> - Cells: 7, 17 & 24 toilets are clogged.</p> <p><u>D2 Block</u> - 2 toilets in day room are clogged, 1 shower runs constantly.</p> <p><u>D1 Block</u> - Both showers run constantly, 1-day room sink runs constantly, leak from sink going to cell 8, Cells 3 and 7 toilets are inoperable, cell doors remain unsecured so inmates can utilize toilet in the day room.</p> <p><u>SHU</u> - Light in hallway is inoperable in front of cells 913-912, hot water is inoperable in cell 911, window in cell 921 cracked.</p> <p><u>B Block</u> - Hot in Cell 2 is inoperable, water in Cell 15 is inoperable, one of the lights doesn't work in cell 21, and the shower is constantly running.</p> <p><u>Booking</u> - Water in ISO/Holding D water is turned off due to plumbing issues.</p> <p><u>Laundry</u> - light in mop closet doesn't work.</p> <p><u>Kitchen</u> - 1 light needs to be replaced, 3 kettle machines are down and have exposed wires (No electricity running through them), light in refrigerator needs to be replaced, dry storage lock needs to be replaced, 2 hand washing sink stations have no hot water and both leak onto the floor and the eye wash station does not drain. <u>It should be noted that technical assistance was provided in the area of sanitation on the FY 2019 annual inspection report.</u></p>



Jason Jouett, TCJS Inspector