

**TEXAS COMMISSION ON JAIL STANDARDS
JAIL INSPECTION REPORT**

Facility Name: Coryell Co. Jail

Date:

April 10, 2019

Item	Section	Paragraph	Comments
1	279	.3	<p>Preventive maintenance, to include necessary repairs, shall be conducted to ensure a safe, secure, and sanitary facility.</p> <p>During the walkthrough of the facility, significant preventative maintenance issues were identified. These include E2 dayroom metal bench cracked, roof leaks in E4 & W4 and cracked/chipped non detention grade mirrors throughout the facility. This issue was noted as technical assistance during the FY 2018 annual inspection.</p>


William T. Phariss, TCJS Inspector